

EXAMPLE OF WORKING LIGHTS

THIS IS ON THE LEFT SIDE OF THE BUILDING.
ONLY CROWN LEFT WORKING

EXAMPLE OF PILLAR AND CROWN NOT WORKING

THIS IS ON THE LEFT SIDE OF THE BUILDING.
THE PILLAR IS WORKING BUT THE NEON CROWN IS NOW BROKEN





EXAMPLE OF PILLAR AND TWO CROWNS BROKEN

THIS IS ON THE RIGHT SIDE OF THE BUILDING.
PILLAR AND BOTH CROWNS ARE BROKEN



2ND EXAMPLE OF PILLAR AND TWO CROWNS BROKEN

THIS IS ON THE RIGHT SIDE OF THE BUILDING.
PILLAR AND BOTH CROWNS ARE BROKEN

EXAMPLE OF UNDER SIDE OF MARQUEE LIGHTS NOT WORKING AT NIGHT





EXAMPLE OF DAMAGE ON THE UNDER SIDE OF THE MARQUEE DURING THE DAY



ONE OF MANY BROKEN ELEMENTS UNDER THE MARQUEE

EXAMPLE OF DRAINAGE ISSUES HAPPENING ON TOP OF MARQUEE





EXAMPLE OF DAMAGE ON TOP OF THE MARQUEE THAT IS CAUSING DECAY AND ELECTRICAL ISSUES FROM WATER GETTING INSIDE